

5/045/046



# United States Department of the Interior

## BUREAU OF LAND MANAGEMENT

Salt Lake District Office  
2370 South 2300 West  
Salt Lake City, Utah 84119



IN REPLY REFER TO:

3809  
U-72294  
(UT-024)

DOGM  
MINERALS PROGRAM  
FILE COPY

JAN 20 1995

CERTIFIED MAIL # 760 541 829  
RETURN RECEIPT REQUESTED

Mr. Sidney K. Hullinger  
McFarland and Hullinger  
P.O. Box 238  
Tooele, Utah 84074

Dear Mr. Hullinger:

On January 12, 1995, Cheryl Martinez and Connie Dotson met with you for an onsite inspection to review your quartzite mining proposal. During the inspection, it was revealed that none of the proposed access routes to the site had been flagged.

We can not consider your Notice complete until you provide this office with the following information:

1. Notification that all of your proposed access routes and cross-country routes have been flagged.
2. What is the total area proposed for disturbance, including cross-country access routes, existing access routes and new access routes? What are the dimensions (length, width, and depth) of all your proposed surface disturbance?
3. Please provide a map showing the access route(s) you prepare to use at your mining site.
4. A signed statement that reclamation of all disturbed areas will be completed to the standard described in 3809.1-3 (d) and that reasonable measures will be taken to prevent unnecessary or undue degradation.

Thank you for your cooperation. If you have any questions or require additional information, please feel free to contact Cheryl Martinez of my staff at (801) 977-4300.

Sincerely,

**/s/ Margaret Wyatt**

Margaret Wyatt  
Pony Express Resource Area Manager

cc: UDOGM  
D. Wayne Hedberg